CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934202
Transaction Date	03 Nov 2026, 12:50:04
Site Name	840 - Emirates Auctions
Transaction Number	58978916 (CC10021) (CC10021)



Vehicle Details

Chassis Number	MR2KT9F33G*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2016
Color	White
Mileage	187087 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE DENTS	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE DENTS	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Sign of front accident	BUMPER FRAME,FENDER FRAME,RADIATOR FRAME SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS ALIGN REPAIRED,PORTION DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED PARTS REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Suspension System		ممتص الصدمات
06.A Arms	BUSHES CRACK	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
07 Interior Condition		الحاله الداخليه
07.A Other	INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
07.B AC Condition	NOT CHECK	المكيف
07.C Door Panel	WORN OUT	لوحة بطانة الباب
07.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae