

Queue Number 2792531

Transaction Date 24 Sep 2026, 13:07:29

Site Name  
840 - Emirates AuctionsTransaction Number  
66713976 (CC10009) (CC10012)

## Vehicle Details

|                   |                 |
|-------------------|-----------------|
| Chassis Number    | WBABS51030***** |
| Specification     | Imported        |
| Make              | BMW             |
| Model             | 330             |
| Model Year        | 2001            |
| Color             | Silver          |
| Mileage           | 112721 Km       |
| Fuel Type         | Petrol          |
| Transmission Type |                 |
| No. Of Cylinders  | 6               |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|                        |                                                                                                                         |                        |
|------------------------|-------------------------------------------------------------------------------------------------------------------------|------------------------|
| 01.A Fenders           | LEFT SIDE REPAINTED                                                                                                     | مدكار                  |
| 01.B Paint             | BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES                                                            | الصبغ                  |
| 01.C Doors             | LEFT SIDE REPAINTED                                                                                                     | أبواب                  |
| 01.D Rusty             | UNDER BODY PARTS ,SUSPENSION PARTS,POWER TRAIN ,RUNNING PARTS RUSTY ,SIGN OF FLOODED                                    | صدأ                    |
| 01.E Floor             | FLOOR RUST PROOFED, MUDDY PORTION DENT                                                                                  | الارضية                |
| 01.F Bumper            | MISALIGN , CRACKED                                                                                                      | دعامية                 |
| 01.G Roof              | CONVERTABLE NOT WORKING PROPERLY , WORN OUT                                                                             | السقف                  |
| 01.H Bonnet            | LEFT SIDE GRILL COVER LOOSE , LOGG FADED                                                                                | غطاء المحرك            |
| 01.I Door Handle &Lock | LEFT SIDE OUTER HANDLE HARD OPENING , RIGHT SIDE NOT OPEN , LOCK COVER MISSING , INNERHANDLE LOOSE, LOCK BUTTON MISSING | مقابض الأبواب والأقفال |

## 02 Chassis Condition

## الشاسي

|              |                                                   |         |
|--------------|---------------------------------------------------|---------|
| 02.A Chassis | CHASSIS PORTION COVERED ,CHECKED VISIBLE AREA /OK | الشاسيه |
|--------------|---------------------------------------------------|---------|

## 03 Engine Condition

## المحرك

|                              |                                                       |                       |
|------------------------------|-------------------------------------------------------|-----------------------|
| 03.A Engine Visual Condition | OIL LEAK REFITTED SHAKING , OVER HEAT , GETTING RUSTY | الحالة النظرية للمحرك |
|------------------------------|-------------------------------------------------------|-----------------------|

## 04 Seats Condition

## المقاعد

|                     |                 |              |
|---------------------|-----------------|--------------|
| 04.A Seat Condition | PORTION DAMAGED | حالة المقاعد |
|---------------------|-----------------|--------------|

| Condition                               | Remarks                                                                                            | الحالة                     |
|-----------------------------------------|----------------------------------------------------------------------------------------------------|----------------------------|
| <b>05 Transmission Condition</b>        |                                                                                                    | <b>الجير</b>               |
| 05.A Gear Box Visual Condition          | REFITTED GETTING RUSTY JERKING                                                                     | الحالة النظرية للجير       |
| 05.B Road Test                          | NOT CHECKED                                                                                        | فحص علي الطريق             |
| <b>06 Tires and Rims Condition</b>      |                                                                                                    | <b>الاطارات</b>            |
| 06.A Front Tyre                         | BOTH SIDE 2023 CRACKED                                                                             | الاطار الامامي             |
| 06.B Rear Tyre                          | RIGHT SIDE 2023 CRACK , LEFT SIDE 2022 CRACKED                                                     | الاطار الخلفي              |
| <b>07 Lights</b>                        |                                                                                                    | <b>الاضاءة</b>             |
| 07.A Head Light                         | LENS FADED                                                                                         | الاضاءة الرئيسية           |
| 07.B Tail Light                         | BOTH SIDE CRACKED , FADED                                                                          | الضوء الخلفي               |
| 07.C Indicator & Hazard light           | FRONT RIGHT SIDE DAMAGED                                                                           | الاشارات                   |
| 07.D Warning Light                      | WARNING LIGHT ON DISPLAY                                                                           | ضوء تحذير                  |
| 07.E Fog light                          | LEFT SIDE MISSING , NOT WORKING , BOTH SIDE COVER MISSING                                          | كشف الضباب                 |
| <b>08 Brake Condition</b>               |                                                                                                    | <b>الفرامل</b>             |
| 08.A Brake Pedal                        | GETTING SPONGY                                                                                     | دواسة الفرامل              |
| <b>09 Suspension System</b>             |                                                                                                    | <b>ممتص الصدمات</b>        |
| 09.A Shock Absorber                     | WEAK FRONT LEAK                                                                                    | ممتص الصدمات               |
| 09.B Arms                               | BUSHES CUT                                                                                         | ازرع                       |
| 09.C Ball Joint                         | BOOT CUT                                                                                           | مفصل كروي                  |
| <b>10 Steering Condition</b>            |                                                                                                    | <b>المقود</b>              |
| 10.A Tie Rod End                        | BOOT CUT                                                                                           | مؤخرة الرودادات            |
| <b>11 Interior Condition</b>            |                                                                                                    | <b>الحالة الداخليه</b>     |
| 11.A Other                              | INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX CRACKED , REAR COVER MISSING                     | اخرى                       |
| 11.B Mirror                             | BOTH SIDE FOLDING NOT WORKING                                                                      | المرآيا                    |
| 11.C AC Condition                       | OK , REAR ADJUSTMENT PORTION MISSING                                                               | المكيف                     |
| 11.D Roof Light                         | BOTH SIDE COVER LIGHTMISSING                                                                       | أنارة السقف                |
| 11.E Power Window Switch And Glass      | FRONT RIGHT SIDE , REAR LEFT SIDE NOT WORKING , FRONT RIGHT SIDE GLASS LOOSE , LOCK BUTTON MISSING | مفتاح النافذه و الزجاج     |
| 11.F Dash Board                         | STRIP PORTION CRACK , GLOVEBOX HANDLE DAMAGED                                                      | لوحة القيادة               |
| 11.G Roof Ceiling                       | PORTION LOOE                                                                                       | بطانه السقف                |
| 11.H Door Panel                         | PORTION CRACKED                                                                                    | لوحة بطانة الباب           |
| 11.I Steering Wheel and control buttons | WORN OUT                                                                                           | عجلة القيادة وازرار التحكم |
| 11.J Gear Shifting Lever                | WORN OUT                                                                                           | ذراع نقل السرعات           |



## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)