



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>29 Jun 2022, 17:27:11</b>
Transaction Number	<b>45202763 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1GKS27KJ9KR339344</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>GMC</b>
Model	<b>Yukon</b>
Model Year	<b>2019</b>
Color	<b>Black</b>
Mileage	<b>74459 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Other	CENTER CONSOLE BOX LOCK BUTTON DAMAGED	اخرى
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	JERKING	حالة الجير النظرى
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Shock Absorber	FRONT BOTH SIDE LEAK	ممتص الصدمات
04.D Suspension Subframe	FRONT BOTH SIDE CROSS MEMEBRE SUPPORT MINOR DENT	
<b>05 Chassis Condition</b>		<b>الشاصي</b>

DEFECT	REMARKS	
05.A Chassis	CHASSIS FAME THCIK RUST PROOFED ,OK	الشاسيه
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Sign of back accident		وجود مؤشر لحادث في الخلف
07.B Fenders	FRONT BOTH SIDE REFITTED & RIGHT SIDE REPAINTED & REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
07.C Bonnet	REFITTED	غطاء المحرك
07.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
07.E Doors	REFITTED	أبواب
07.F Other	REAR LEFT SIDE QUARER PANEL REPAIRED , FRONT BUMPER FRAME REFITTED	اخري
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Brake Pedal	WEAK	دواسة الفرامل
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2020/2021	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2020/2021	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.