



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Dec 2021, 17:51:48
Transaction Number	99076703 (CC10006)	Queue Number	312309



Chassis Number	JTJHY00W1F4182452
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LX 570
Model Year	2015
Color	White
Mileage	98344 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Seats Condition		المقاعد
01.A Seat Condition	LOOSE&REAR LEFT NECK REST DAMAGED	حالة المقاعد
01.B Seat Belt	OK	حزام الأمان
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK&GRILL CRACKED,LOOSE&REAR RIGHT MISSING	المكيف
02.B Mirror	RIGHT SIDE FOLDING NOT WORKING,LOOSE,LOWER COVER MISSING &LEFT SIDE GETTING FADED	المرايا
02.C Sunroof	NOT WORKING PROPERLY	فتحت سقف
02.D Power Window Switch	REAR BOTH POWER WINDOW NOT WORKING FROM MAIN SWITCH	مفتاح النافذه
02.E Floor Matting	REAR LEFT SIDE RUCKER PANEL COVER PART MISSING	فرش الأرضيه
03 Engine Condition		المحرك
03.A Engine Condition	SIGN OF MINOR OIL WET	حالة المحرك
03.B Other	ENGINE STARTER BOLT LOOSE	اخرى
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OK	الجير

DEFECT	REMARKS	
05 Suspension System		ممتص الصدمات
05.A Shock Absorber	REAR LEFT SIGN OF OIL LEAK&HYDRAULIC SYSTEM NOT WORKING	ممتص الصدمات
05.B Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	WORNOUT	ازرع المساحات والشفرات
07 Body		جسم المركبة
07.A Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
07.B Fenders	FRONT &REAR BOTH SIDE FENDER REPAINTED,PORTION REPAIRED&FRONT FENDER REFITIED,MISALIGN	مدكار
07.C Doors	RIGHT BOTH SIDE DOOR REPAINTED,PORTION REPAIRED&FRONT LEFT SIDE REPAINTED	أبواب
07.D Bumper	REPAINTED	دعامية
07.E Bonnet	REFITIED BOLT LOOSE,MISALIGN	غطاء المحرك
07.F Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY MINOR DENT,SCRATCHES	الصبغ
07.G Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING RUSTY	صدأ
07.H Fuel Tank	COVER DENT	خزان الوقود
07.I Pillars	RIGHT SIDE D/PILLAR REPAIRED	القوائم
08 Chassis Condition		النشاصي
08.A Chassis	OK	النشاصيه
09 Brake Condition		الفرامل
09.A Hand Brake	NOT WORKING	فرامل اليد
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
10.C Spare Tire &Tools	SPARE TIRE & TOOLS MISSING	الاطار الاحتياطي و العدة
11 Lights		الاضاءة
11.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
11.B Head Light	LENS MINOR FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.