CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998610
Transaction Date	16 Nov 2026, 16:51:59
Site Name	840 - Emirates Auctions
Transaction Number	91992985 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JTEHT05J15*******
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2005
Color	White
Mileage	796663 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES,PORTION RUSTY,PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT REFITTED , RUBBER DRY CRACK	الارضية
01.E Bumper	MISALIGN,GRILL PORTION DAMAGED	دعامية
01.F Roof	BOTH SIDE STRIP MISSING	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE C/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	REFITTED,PORTION HOLE	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION DENT , REAR CROSS MEMBER RUSTY HOLE	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	REAR SEAT MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	HEADRES MODIFIED / CUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL WET REFITTED, GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	BOTH SIDE BRACKET PORTION DAMAGED , PORTION REPAIRED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPASLY	ضوء تحذير
08.C Fog light	NOT WORKING	كشاف الضباب
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY	دواسة الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	REAR LEAK	ممتص الصدمات
10.B Arms	BUSHES CRACKED	ازرع
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY & CENTER CONSOLE BOX COVER WORN OUT	اخري
11.B AC Condition	NOT COOLING	المكيف
11.C Power Window Switch And Glass	SWITCH LOOSE , REAR RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.D Roof Ceiling	LOOSE	بطانه السقف
11.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	DUST COVER PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae