

Queue Number 2625410

Transaction Date 08 Aug 2026, 11:55:57

Site Name
840 - Emirates AuctionsTransaction Number
25510645 (CC10021) (CC10011)

Vehicle Details

Chassis Number	3FA6POHR6D*****
Specification	Imported
Make	Ford
Model	Fusion
Model Year	2018
Color	Red
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED, CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.F Bonnet	REFITTED,STAY ROD MISSING,MISALIGN,OPEN HANDLE DAMAGED	غطاء المحرك
01.G Pillars	BOTH SIDE A/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	NOT OPENING	صندوق
01.I Door Handle & Lock	FRONT LEFT SIDE KEY COVER MISSING	مقابض الأبواب والأقفال
01.J Sign of front accident	BUMPER FRAME ,FENDER FRAME , BULKHEAD , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident	WHEEL ARCH REPAIRED	وجود مؤشر لحادث في الجانب
01.L Sign of back accident	BACK PANEL, REAR COMPARTMENT, QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis Extension	REAR LEFT SIDE CHASSIS EXTENSION REPAIRED	تمديدات الشاسي
02.B Chassis	FRONT LEFT SIDE REPAIRED, DENT	الشاسيه

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECK, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENTS & SCRATCHES, WHEEL HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS RUSTY, SOGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Roof Ceiling	LOOSE	بطانة السقف
10.D Door Panel	WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT, PANEL DAMAGED	ذراع نقل السرعات
11 Battery Condition		حالة البطارية
11.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae