CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937933
Transaction Date	02 Nov 2026, 15:48:17
Site Name	840 - Emirates Auctions
Transaction Number	89764004 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5NPE24AF3H*******
Specification	Imported
Make	Hyundai
Model	Sonata
Model Year	2017
Color	Grey
Mileage	77691 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE QUARTER PANEL ROOF RAIL REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REAR BOTH SIDE REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED. ,LOGO MISSING	دعامية
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT ,REAR EXTENSION END DENT , GETTING RUTY.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.CASE PORTION CUT .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED. .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED PUNCTURE .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,RIGHT SIDE CRACKED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY.	اخري
09.B AC Condition	NOT COOLING.	المكيف
09.C Dash Board	LEATEHR REPLACED REPAIRED .,	لوحة القياده
09.D Roof Ceiling	PORTION CUT .	بطانه السقف
09.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.F Air Bag	OPEN REFITTED .	وسائد هوائية
09.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.