

Queue Number 2841808

Transaction Date 07 Oct 2026, 13:20:28

Site Name
840 - Emirates AuctionsTransaction Number
42964585 (CC10006) (CC10006)

Vehicle Details

Chassis Number	4P3XTGA2WD*****
Specification	GCC Specification
Make	Mitsubishi
Model	ASX
Model Year	2013
Color	Maroon
Mileage	122622 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NO CHECK	مدكار
01.B Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PARTS MINOR DENT , MUDDY	الارضية
01.E Bumper	MISALIGN , SCRATCHES , PORTION FADED	دعامية
01.F Trunk	NOT OPENING , MISALIGN	صندوق
01.G Door Handle & Lock	REAR RIGHT SIDE OUTER LOCK HANDLE DAMAGE	مقابض الأبواب والأقفال
01.H Sign of back accident	RIGHT SIDE QUARTER PANEL REPAIRED , BUMPER FRAME BEND	وجود مؤشر لحادث في الخلف
01.I Vehicle Color	BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	COVERD, CHECKED VISIBLE AREA ONLY OK/ GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED, SHAKING, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR JERKING GETTING RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSHES CRACKED	كرسي الجير

Condition	Remarks	الحالة
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	FRONT BOTH SIDE 2018 EXPIRED DAMAGE	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018 EXPIRED DAMAGE	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT , PANEL PORTION LOOSE , INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT COOLING	المكيف
10.C Roof Light	LEFT SIDE LIGHT COVER DAMAGE , REAR NOT WORKING	أنارة السقف
10.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB PORTION WORN OUT , SHIFTER COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

