



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	01 Aug 2022, 11:25:35
Transaction Number	94302803 (CC10006)	Queue Number	312309



Chassis Number	WP1ZZZ92ZBLA03879
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne
Model Year	2011
Color	Black
Mileage	85185 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Power Window Switch	REAR LEFT SIDE WINDOW,CURTAIN NOT WORKING	مفتاح النافذه
01.B AC Condition	OK & ADJUSTMENT BUTTON MISSING	المكيف
01.C Door Panel	PORTION LOOSE	لوحة بطانة الباب
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019 WORN OUT,CRACKED	الاطار الخلفي
03 Chassis Condition		الشاسي
03.A Chassis Number	AVOID PUNCHING NUMBER GETTING RUSTY	رقم القاعدة
03.B Chassis	CHECKED VISIBLE AREA OK	الشاسيه
04 Body		جسم المركبة
04.A Fenders	FRONT RIGHT SIDE PORTION REPAINTED	مدكار
04.B Doors	REPAINTED,PORTION REPAIRED	أبواب
04.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
04.D Trunk	PORTION REPAIRED,REPAINTED	صندوق
04.E Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED	الارضيه

DEFECT	REMARKS	
CHECKED VISIBLE AREA		
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظري
05.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Engine Condition		المحرك
06.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
06.B Smoke	BLACK SMOKE	دخان
07 Suspension System		ممتص الصدمات
07.A Arms	LOWERARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.