



### Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	: 1
Transaction Number	: 24400213	Plate Category	: PRIVATE
Transaction Date	: 22 FEB 2021 11:52:08	Plate Number	: 38003
Queue Number	: 300239	Import Doc. Ref.	:
Chassis Number	: MA3WB5B20JA398044	Manufacturer/Model	: SUZUKI/BALENO
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLUE
Service / Indicator	: DSC AUCTION	Mileage	: 25709

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
05 Body		الهيكل
05.02 - Paint		الصبغ
05.05 - Bumpers		الدعامية
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
09 Auction		الفحص الكامل
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صبغ في المركبة
		RR BUMPER & B/FRAME REPD
		BACK PANEL & FLOORING,Q/PANEL REPD
		REAR CHASSIS EXTENSION END DENT & REPD
		TAIL DOOR,REAR Q/PANEL REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط  
تسجيل غير مسؤولة عن العيوب الخفية