





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18543315	Plate Category	: PRIVATE
Transaction Date	: 16 NOV 2019 15:50:41	Plate Number	: 2105 EA
Queue Number	: 118879	Import Doc. Ref.	:
Chassis Number	: WAUAYA8X8BB072105	Manufacturer/Model	: AUDI/A1
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Centerlink, Left And Right		ربلات ذراع التوجيه
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
04.08 - Spare Tires		الاطار الاحتياطي
05 Body		الهيكل
05.02 - Paint		الصبغ
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18543315	Plate Category	: PRIVATE
Transaction Date	: 16 NOV 2019 15:50:41	Plate Number	: 2105 EA
Queue Number	: 118879	Import Doc. Ref.	:
Chassis Number	: WAUJAYA8X8BB072105	Manufacturer/Model	: AUDI/A1
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition