



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Jan 2023, 16:58:22</b>
Transaction Number	<b>97443536 (CC10009)</b>	Queue Number	<b>658695</b>



Chassis Number	<b>MDHAK3CROGG505080</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Micra</b>
Model Year	<b>2016</b>
Color	<b>White</b>
Mileage	<b>211413 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Dash Board	CONSOLE BOX PORTION DAMAGED	لوحة القيادة
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C AC Condition	OK	المكيف
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT CROSS MEMBER REPAIRED	اخرى
02.B Fenders	REFITTED	مدكار
02.C Bumper	MISALIGN	دعامية
02.D Bonnet	REFITTED	غطاء المحرك
02.E Paint	BODY TOTALY REPAINTED REPAIRED EXCEPT ROOF & MINOR DENT,SCRATCHES	الصبغ
02.F Doors	REFITTED	أبواب
02.G Sign of front accident		وجود مؤشر لحادث في المقدمة
02.H Floor	UNDER FLOOR MUDDY	الارضية
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

DEFECT	REMARKS	
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Gear Box Mount	MOUNT CRACK	كرسي الجير
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Visual Gear Box Condition	REFITTED	حالة الجير النظرى
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Mount	MOUNT CRACK	كرسي
05.B Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظرى
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED	الشاسيه
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2022	الاطار الامامي
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	DRIVER SEAT COVER PORTION DAMAGED & REAR LOOSE	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	P 92118 Dubai Private
Chassis No :	MDHAK3CROGG505080
Vehicle Make :	NISSAN
Vehicle Model :	MICRA
Vehicle Class :	Light Vehicle
Body Type :	HATCHBACK
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	211230 Kms.
Origin : India	Model Year : 2016
Gear Type : Automatic	Engine Size : 1500 CC
Engine No : HR15774718D	Horse 80
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1450 Kgs.	Empty 1000 Kgs.
	Weight :

Certificate Number :	1-TAS-2023-18548967		
Inspection Date :	14-01-2023		
Certificate Print Date :	14-01-2023		
Services :	Renewal Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	6 min 1 sec		
Appointment Ref Number :	--		
Start Time :	11:14	End Time :	11:20
Lane :	02	Token No. :	127
Attempt :	2	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

27360 KM	1537 L	5334 AED	3.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Vehicle on Petrol CO Reading	Vehicle on Petrol HC Reading
0 %	2 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1500	1200	

## Inspection Remarks:

MINOR BODY DENTS & SCRATCHES.FRONT FENDER FRAME RADIATOR SUPPORT BULK HEAD BUMPER FRAME LEFT SIDE CHASSIS END REPAIRED.

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
30544	Cash	18548967	AED 70 Collected on 14/01/2023
Parking Slot No	Service Name	Attempt	Received by
--	Renewal Test	2	Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

