CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2924800
Transaction Date	31 Oct 2026, 12:49:46
Site Name	840 - Emirates Auctions
Transaction Number	26872612 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WDD2221571*******
Specification	Imported
Make	Mercedes
Model	S 400
Model Year	2015
Color	Black
Mileage	223192 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	MINOR DENTS SCRATCHES ON BODY	الصبغ
01.B Doors	FRONT LEFT SIDE REFITTED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MINOR MISALIGN	دعامية
01.F Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OILLEAK PARTS REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	REAR LEFT SIDE GUIDE HOLDER DAMAGED	حزام الأمان
04.B Seat Condition	FRONT BOTH SIDE SEAT BACK COVER PORTION LOOSE,RIGHT SIDE NECK REST BARCKET COVER PORTION DAMAGED PART MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK PARTS REFITTED MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH FADED	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER LOCK DAMAGED,CUP HOLDER SLIDING COVER STUCK	اخري
10.B AC Condition	OK	المكيف
10.C Audio	TOUCH PAD NOT WORKING PROPERLY	صوتيات
10.D Dash Board	LEATHER PORTION LOOSE WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
10.F Door Panel	PORTION GETTING WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.H Sunroof	NOT WORKING,FRONT CURTAIN NOT WORKING STUCK	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae