



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 May 2022, 18:01:54
Transaction Number	65457287 (CC10008)	Queue Number	312309



Chassis Number	SALWR2RE2JA194304
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Supercharged
Model Year	2018
Color	Silver
Mileage	70163 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظري
03 Body		جسم المركبة
03.A Doors	FRONT RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب
03.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.C Floor	FRONT FLOOR METAL COVER DAMAGED , FLOOR COVERED CHECKED VISIBLE AREA OK	الارضيه
03.D Rusty	UNDER BODY PARTS GETTIG MINOR RUSTY	صدأ
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05 Engine Condition		المحرك

DEFECT	REMARKS	
05.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
06 Chassis Condition		الشاسي
06.A Chassis	CHEKCED , VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.