



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Jan 2022, 15:06:57
Transaction Number	67275833 (CC10006)	Queue Number	312309



Chassis Number	JMYSTCY4AEU714813
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Lancer
Model Year	2014
Color	Silver
Mileage	230093 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	LEFT SIDE BOTH REPAINTED,PORTION REPAIRED	أبواب
01.B Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.C Bumper	REAR BUMPER FRAME MINOR DENT	دعامية
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Other	FRONT RADIATOR SUPPORT ,BULK HEAD ,BUMPER FRAME REPAIRED	اخرى
01.F Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED,MISALIGN	مدكار
01.G Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.H Trunk	REPAINTED,PORTION REPAIRED	صندوق
02 Interior Condition		الحالة الداخلية
02.A Mirror	ADJUSTMENT NOT WORKING PROPERLY	المرايا
02.B AC Condition	FRONT LEFT SIDE GRILL DAMAGED	المكيف
02.C Steering Wheel and control buttons	WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم
03 Lights		الاضاءة

DEFECT	REMARKS	
03.A Head Light	LENS FADED & LEFT SIDE PARK LIGHT NOT WORKING	الاضاءة الرئيسية
03.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2020 CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020 CRACKED	الاطار الخلفي
05 Engine Condition		المحرك
05.A Visual Engine Condition	OK	حالة المحرك النظري
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	OK	حالة الجير النظري
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	REAR SHOCK ABSORBER OIL LEAK	ممتص الصدمات
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.