





### Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 19287882	Plate Category	: PRIVATE
Transaction Date	: 26 FEB 2020 12:58:42	Plate Number	: 12439 EA
Queue Number	: 150159	Import Doc. Ref.	:
Chassis Number	: LUCCR2625F3412439	Manufacturer/Model	: HONDA/ACCORD
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: OTHERS
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Centerlink, Left And Right		ربلات ذراع التوجيه
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.01 - Rusty		الصدأ
05.02 - Paint		الصبغ
05.05 - Bumpers		الدعامية
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition	OK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OK	حالة المحرك - الدخان
06.21 - Battery Condition	DEAD	حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات



### Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 19287882	Plate Category	: PRIVATE
Transaction Date	: 26 FEB 2020 12:58:42	Plate Number	: 12439 EA
Queue Number	: 150159	Import Doc. Ref.	:
Chassis Number	: LUCCR2625F3412439	Manufacturer/Model	: HONDA/ACCORD
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: OTHERS
Service / Indicator	: DSC AUCTION		

#### Statement of Vehicle Condition

09.06 - Chassis Ok

الشاصي جيد

09.14 - Sign Of Front Accident

أثر حادث في مقدمة المركبة

The Test Certificate Shows the test Result at the time of inspection only.