



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 13:15:45
Transaction Number	12930012 (CC10006)	Queue Number	312309



Chassis Number	JN8FY1NY9KX033861
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2019
Color	Gold
Mileage	98540 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Roof Ceiling	PORTION LOOSE	بطانه السقف
01.C Floor Matting	REMOVE FRONT RIGHT SIDE MATTING & PILLAR COVER FOR RECHECK	فرش الأرضيه
02 Body		جسم المركبة
02.A Paint	BODY TOTALLY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.B Pillars	FORN LEFT SIDE RIGHT SIDE A/B/C PILLAR REPAIRED SUSPECT CUT, ROCKER PANEL REPAIRED,REPAINTED	القوائم
02.C Sign of front accident		وجود مؤشر لحادث في المقدمة
02.D Sign of side accident		وجود مؤشر لحادث في الجانب
02.E Other	FROTN BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT COIL PANEL REAIRED	اخرى
02.F Floor	REMOVE PAINT PAST FROM FAIR WALL COIL PANEL FOR RECHECKE PROEPRLY	الارضيه
02.G Roof	ROOF & ROOFRAILL REPAIRED	السقف
03 Transmission Condition		الجير

DEFECT	REMARKS	
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03.C Visual Gear Box Condition	OPEN REFITTED OIL LEAK	حالة الجير النظري
04 Chassis Condition		الشاسي
04.A Chassis	FORNT BOTH SIDE CHASSIS BEND . REAR BOTH SIDE CHASSIS BULGED	الشاسيه
04.B Chassis Number	MANUFACTUR PLATE REFITTED	رقم القاعدة
05 Engine Condition		المحرك
05.A Smoke	MINOR BLACK SMOKE	دخان
05.B Visual Engine Condition	OPEN REFITTED OIL LEAK	حالة المحرك النظري
05.C Mount	MOUNT RUBBER CRACKED	كرسي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JN8FY1NY9KX033861
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Golden, Gray
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	98536 Kms. x
Origin : Japan	Model Year : 2019
Gear Type : Manual	Engine Size : 4800 CC
Engine No : TB48117762	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 3175 Kgs.	Empty 2000 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17261074		
Inspection Date :	24-07-2022		
Certificate Print Date :	24-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	3 min 51 sec		
Appointment Ref Number :	--		
Start Time :	14:05	End Time :	14:08
Lane :	02	Token No. :	193
Attempt :	2	Prints No. :	1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate in 12 Months)

591216 KM	60834 L	191019 AED	145.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks:

RIGHT SIDE MIDDLE CHASSIS REPAIRED/DENT .FRONT CROSSMEMBER,RIGHT SIDE FENDER FRAME,APRON,BULKHEAD,RIGHT SIDE DOOR A,B PILLAR,ROCKER PANEL,RUNNING BOARD,FLOORING REPAIRED. //OLD //



Odometer Record
Replace Events Date

31/05/2022

Payment Details

Inspection Performed by 30544	Payment Method Cash	Transaction Number 17261074	Service Fees AED 70 Collected on 24/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.