



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	04 Jan 2023, 16:58:32
Transaction Number	23714019 (CC10009)	Queue Number	652763



Chassis Number	W1N4M4HB7LW025569
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	GLB 250
Model Year	2020
Color	White
Mileage	22605 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Sign of front accident		وجود مؤشر لحادث في المقدمة
01.B Paint	BODY MINOR SCRATCHES	الصبغ
01.C Bumper	FRONT BUMPER FRAME BULK HEAD RADIATOR ASSEMBLY REFITTED	دعامية
01.D Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة المحرك النظري
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظري
<b>04 Chassis Condition</b>		<b>الشاسي</b>
04.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY /OK	الشاسيه
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	BOTH SIDE LOWER DENT	ازرع

DEFECT	REMARKS	
05.B Ball Joint	BOOT CUT	مفصل كروي
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2019,	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.