



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Sep 2021, 18:06:33
Transaction Number	81273295 (CC10006)	Queue Number	312309



Chassis Number	WDDKJ7CB1AF030639
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	E 61 Brabus
Model Year	2010
Color	White
Mileage	0

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERD	الارضية
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	PORTION REPAIRED , REPAINTED	غطاء المحرك
01.G Other	FRONT BUMPER BRACKET REPAIRED	اخرى
<b>02 Chassis Condition</b>		<b>الشاصي</b>
02.A Chassis	VISABLE AREA OK	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	MINOR OIL LEAK	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Other	OK	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box	OK	الجير
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Other	OK	اخرى

DEFECT	REMARKS	
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>10 Interior Condition</b>		<b>الاجزاء الداخلية</b>
10.A Other	OK	اخرى
10.B Mirror	AUTO NOT WORKING	المرآيا
10.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.