



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **05 Sep 2022, 18:01:43**
 Transaction Number **21734305 (CC10008)** Queue Number **312309**



Chassis Number **WBAFR1101DC861256**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **BMW**
 Model **530I**
 Model Year **2013**
 Color **White**
 Mileage **420742 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	LOW COOLING	المكيف
01.B Dash Board	DASH BOARD DAMAGED SIDE COVERS LOOSE	لوحة القيادة
01.C Audio	SCREEN MISSING,	صوتيات
01.D Roof Ceiling	LOOSE	بطانه السقف
02 Engine Condition		المحرك
02.A Other	START BUTTON MODIFIED	اخرى
02.B Visual Engine Condition	MINOR OIL LEAK,REFITTED,SHAKING	حالة المحرك النظري
02.C Smoke	WHITE SMOKE	دخان
03 Lights		الاضاءة
03.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CUT	حالة المقاعد
05 Body		جسم المركبة
05.A Fenders	REAR LEFT SIDE REPAIRED,REPAINTED & FRONT REFITTED	مدكار
05.B Doors	PORTION REPAIRED,REPAINTED	أبواب

DEFECT	REMARKS	
05.C Bonnet	REPAIRED,REPAINTED,REFITTED	غطاء المحرك
05.D Trunk	REPAIRED,REPAINTED	صندوق
05.E Roof	HAVE HOLE	السقف
05.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
05.G Floor	FLOOR FENDER CHASSIS COVERED CHECKED VISIBLE AREA ONLY	الارضية
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	MINOR OIL LEAK,REFITTED	حالة الجير النظري
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
09.B Arms	LOWER ARM BUSHES CUT	ازرع
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
10.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.