

Queue Number 2792264

Transaction Date 23 Sep 2026, 16:02:38

Site Name
840 - Emirates AuctionsTransaction Number
28830454 (CC10010) (CC10025)

Vehicle Details

Chassis Number	WVWFK2AU6F*****
Specification	GCC Specification
Make	Volkswagen
Model	Golf
Model Year	2015
Color	White
Mileage	135679 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	FLOOR CHASSIS COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY,	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	FIBER PORTION FADED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED ,CEHCKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED ,OIL LEAK . ABNORMAL NOISY.	الحالة النظرية للمحرك
------------------------------	--------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED ,OIL WET GET JERKING.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING MESSAGE ON IN CLUSTER.	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك و طنايبير الفرامل
09 Steering Condition		المقود
09.A Axle	AXLE BOOT GREASE LEAKING.	اكسلات
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK , REAR GRILL ADJUSTMENT PORTION MISSING	المكيف
10.C Power Window Switch And Glass	SWITCH PORTION DAMAGED	مفتاح النافذه و الزجاج
10.D Dash Board	GRILL PORTION LOOSE	لوحة القيادة
10.E Sun Visor	RIGHT SIDE BRACKET DAMAGED LOOSE	حاجب الشمس
10.F Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم
10.G Sunroof	NOT WORKING PROPERY & CURTAIN LOOSE	فتحت سقف
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتساوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

