CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945023
Transaction Date	04 Nov 2026, 14:39:53
Site Name	840 - Emirates Auctions
Transaction Number	48020829 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5TDKZ3DC2H*******
Specification	Imported
Make	Toyota
Model	Sienna
Model Year	2017
Color	Grey
Mileage	137438 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED REFITTED ,REAR REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED REFITTED, FADED.	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED BEND GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION LOOSE ,REAR HAND REST DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH ISDE 2025 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 DRY CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	OK	المكيف
10.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.D Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae