

Queue Number

2877714

Transaction Date

17 Oct 2026, 11:17:54

Site Name

840 - Emirates Auctions

Transaction Number

44958385 (CC10026) (CC10026)



Vehicle Details

Chassis Number	KNDJP3A53F*****
Specification	Imported
Make	Kia
Model	Soul
Model Year	2015
Color	Blue
Mileage	218174 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED , DENTS SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY HOLE	صدأ
01.C Floor	UNDER FLOOR PARTS RUSTY HOLE , DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION SCRATCHES	دعامية
01.E Bonnet	REFITTED , PORTION REPAINTED , MISALIGN	غطاء المحرك
01.F Trunk	PORTION REPAINTED , NOT OPENING	صندوق
01.G Sign of front accident	BUMPER FRAME , BULK HEAD , RADAITOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END OPEN DETACHED , DENT , PORTION RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED , PARTS GETTING RUSTY , MUDDY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED, PARTS GETTING RUSTY , MUDDY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
-----------------	----------------	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القيادة
08.D Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae