

Queue Number 2691428

Transaction Date 29 Aug 2026, 12:47:30

Site Name
840 - Emirates AuctionsTransaction Number
56647087 (CC10009) (CC10012)

Vehicle Details

Chassis Number 2G1135S34K*****
 Specification GCC Specification
 Make Chevrolet
 Model Impala
 Model Year 2019
 Color White
 Mileage 70672 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED, MINOR DENT SCRATCHES	الصبغ
01.C Bonnet	PORTION REPAINTED , SHOCK NOT WORKING	غطاء المحرك
01.D Trunk	REPAINTED PORTION REPAIRED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA /OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK, PARTS REFITTED	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR OIL LEAK, PARTS REFITTED	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Wipers and Arms		المساحات
06.A Other	TANK CAP MISSING.	اخرى
07 Interior Condition		الحالة الداخلية
07.A AC Condition	OK	المكيف
07.B Sun Visor	LEFT SIDE COVER MIRROR MISSING , RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
07.C Door Panel	PORTION CRACK	لوحة بطانة الباب
08 Battery Condition		حالة البطارية
08.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae