



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **19 Jul 2022, 13:25:13**
 Transaction Number **64397887 (CC10006)** Queue Number **312309**



Chassis Number **JN8AY2NYXE9060012**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Patrol**
 Model Year **2014**
 Color **Silver**
 Mileage **1097 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES	الصبغ
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	REFITTED	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Exhaust System		نظام العادم
04.A Other	EXHAUST MODIFIED	اخرى
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
06 Chassis Condition		الشاسي
06.A Chassis	OK	الشاسيه

DEFECT	REMARKS	
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	أزرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Suspension Subframe	SUSPENSION MODIFIED	
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Engine Condition		المحرك
09.A Visual Engine Condition	MINOR OIL LEAK , REFITTED	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.