CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890794
Transaction Date	20 Oct 2026, 16:41:07
Site Name	840 - Emirates Auctions
Transaction Number	59717562 (CC10013) (CC10025)



Vehicle Details

Chassis Number	JN6BE6DS7F*******
Specification	GCC Specification
Make	Nissan
Model	NV350
Model Year	2015
Color	White
Mileage	462067 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES PORTION RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUSTY HOLE DAMAGED	الارضية
01.D Bumper	MISALIGN DAMAGED	دعامية
01.E Roof	RUSTY HOLE	السقف
01.F Trunk	NOT CLOSE	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CROSS MEMBER RUSTY HOLE PORTION BULGED DENT	الشاسيه
02.B Chassis Number	VIN AREA RUSTY	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED , PARTS GETTING RUTSY , MUDDY DIRTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION DAMAGED , REAR LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	REFITTED , MUDDY , DIRTY , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED , RIGHT SIDE DAMAGED	الاضاءة الرئيسية
08.B Tail Light	PORTION DAMAGED	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
09.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B AC Condition	NOT COOLING	المكيف
10.C Roof Light	COVER PORTION DAMAGED , REAR NOT WORKING	أنارة السقف
10.D Audio	NOT WORKING	صوتيات
10.E Dash Board	PORTION SCRATCHES	لوحة القياده
10.F Door Panel	PORTION WORN OUT , COVER PORTION LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae