



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19924429	Plate Category	:
Transaction Date	: 08 JUN 2020 13:22:42	Plate Number	:
Queue Number	: 184131	Import Doc. Ref.	: 605956 EA
Chassis Number	: 5N1BA0ND3BN605956	Manufacturer/Model	: NISSAN/ARMADA
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION	Mileage	: 97185

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Failed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
17 Shock Absorbers Test			فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed		فحص مخمد الصدمات
VISUAL TEST:			
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		ALL TYRES WEAK OLD 2016.	الاطارات الامامية
05 Body			الهيكل
05.01 - Rusty		CHASSIS FRAME, UNDER FLOOR PARTS, SUSPENSION PARTS RUSTY.	الصدأ
05.06 - Roof		SUN ROOF NOT SLIDING.	السقف
06 General Items			الاشياء العامة
06.21 - Battery Condition		DISCHARGED, ENGINE GETTING OFF.	حالة البطارية
07 Remarks			ملاحظات
07.04 - Others		ROAD TEST NOT DONE DUE TO ENGINE GETTING OFF.	ملاحظات اخرى
09 Auction			الفحص الكامل
09.06 - Chassis Ok		OK	الشاسي جيد
09.18 - A/C Not Cooling			عطل في المكيف
09.25 - Body Repainted		BODY PORTIONS REPAINTED.	أثر صبغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.			
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط			