





Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19506101	Plate Category	:
Transaction Date	: 23 MAR 2020 13:39:55	Plate Number	:
Queue Number	: 162557	Import Doc. Ref.	: 31316 EA
Chassis Number	: JN1AR5EF5AM231316	Manufacturer/Model	: NISSAN/GTR
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE-BLACK
Service / Indicator	: DSC AUCTION	Mileage	: 93924

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
		FRONT LHS AXLE INNER BOOT CUT.
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		FRONT TYRES 2019 & REAR TYRES 2019.
05 Body		الهيكل
05.02 - Paint		الصبغ
		BONNET & ROOF TOP,TRUNK LID BLACK STICKERED.
05.04 - Fenders		المدكار
		FRONT RHS FENDER FRAME,APRON ALIGNED REPAIRED STILL MINOR DENT.
05.05 - Bumpers		الدعامية
		FRONT BUMPER FRAME,BUMPER,FENDERS REFITTED.
05.07 - Floor		الارضية
		UNDER FLOOR,RUNNING BOARDS DENTS.
05.12 - Side Safety Frame		الواقيات الجانبية
		FRONT BULK HEAD ASSEMBLY & BONNET REFITTED.
06 General Items		الاشياء العامة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		ENGINE RADIATOR COOLANT LEAKS & GETTING OVER HEAT.
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		GTR MALFUNCTIONS NOT WORKING.
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.10 - Engine Oil Leaking		تهريب زيت المحرك
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.19 - Gear Ok	OK	الجير جيد



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19506101	Plate Category	:
Transaction Date	: 23 MAR 2020 13:39:55	Plate Number	:
Queue Number	: 162557	Import Doc. Ref.	: 31316 EA
Chassis Number	: JN1AR5EF5AM231316	Manufacturer/Model	: NISSAN/GTR
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE-BLACK
Service / Indicator	: DSC AUCTION	Mileage	: 93924

Statement of Vehicle Condition

09.20 - Differential Not Ok	REAR DIFFERENTIAL VIBRATION & ABNORMAL NOISE.	عطل في الدفرنش
09.25 - Body Repainted	B/S FENDERS, DOORS, RR Q/PANELS PORTIONS REPAINTED.	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط</p>		