



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:15:08
Transaction Number	85873909 (CC10006)	Queue Number	312309



Chassis Number	1FAHP60A52Y112524
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Thunder Bird
Model Year	2002
Color	Red
Mileage	138634 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Trunk	REFITTED	صندوق
01.B Fenders	REAR BOTH SIDE REPAINTED,PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار
01.C Floor	UNDER BODY TAKE RUST PROOF	الارضية
01.D Bonnet	REFITTED	غطاء المحرك
01.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED, MINOR ,SCRATCHES	الصبغ
01.F Doors	REPAINTED,PORTION REPAIRED	أبواب
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
02.B Dash Board	DASHBOARD LOWER COVER LOOSE & HAVE EXTRA SWITCH	لوحة القيادة
02.C Steering Wheel and control buttons	AUDIO BUTTON NOT WORKING ON STEERING &HORN BUTTON MODIFIED	عجلة القيادة وازرار التحكم
02.D Mirror	ADJUSTMENT NOT WORKING PROPERLY & ADJUSTMENT BUTTON DAMAGED	المرآيا
03 Battery Condition		حالة البطارية

DEFECT	REMARKS	
03.A Battery Condition	OK	حالة البطارية
04 Chassis Condition		الشاسي
04.A Chassis	OK	الشاسيه
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2018 & MINOR CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
05.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
06 Seats Condition		المقاعد
06.A Seat Belt	OK	حزام الأمان
06.B Seat Condition	LEFT SEAT SIDE COVER LOOSE	حالة المقاعد
07 Wipers and Arms		المساحات
07.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
08 Steering Condition		المقود
08.A Steering Oil	OIL LEAK	زيت المقود
08.B Tie Rod End	FRONT & REAR BOOT CUT	مؤخرة الرودادت
08.C Steering Boot	BOOT CUT	ربلة المقود
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
10 Engine Condition		المحرك
10.A Other	RPM GUAGE NOT WORKING PROPERLY	اخرى
10.B Engine Condition	OIL LEAK	حالة المحرك
11 Lights		الاضاءة
11.A Head Light	BOTH SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
12 Suspension System		ممتص الصدمات
12.A Other	FRONT & REAR STABLIZER LINK BOOT CUT	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.