CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2887916
Transaction Date	20 Oct 2026, 11:27:18
Site Name	840 - Emirates Auctions
Transaction Number	21102921 (CC10026) (CC10026)



Vehicle Details

Chassis Number	5N1AL0MM7D*******
Specification	GCC Specification
Make	Infiniti
Model	JX 35
Model Year	2013
Color	Grey
Mileage	368830 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOORTHICK RUST PROOFED PORTION DENTS, MUDDY	الارضية
01.E Bonnet	REFITTED , MISALIGN , STAY SHOCK WEAK NOT WORKING	غطاء المحرك
01.F Trunk	NOT OPENING	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis Extension	LEFT SIDE CHASSIS EXTENSION REPAIRED , DENT	تمديدات الشاسي
02.B Chassis	FRONT LEFT SIDE OUTER CHASSIS SKIRT REPAIRED , DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT , EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025 & LEFT SIDE DAMAGE	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 & RIGHT SIDE DAMAGE	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	PORTION SCRATCHES	الضوء الخلفي
08 Brake Condition		**الفرامل**
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		**ممتص الصدمات**
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		**المقود**
10.A Steering Box	MINOR OIL LEAK	جهاز المقود
10.B Tie Rod End	PORTION WORN OUT	مؤخرة الرودات
11 Interior Condition		**الحاله الداخليه**
11.A Other	CENTER CONSOLE PANEL COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Dash Board	PORTION WORN OUT	لوحة القياده
11.D Roof Ceiling	PORTION LOOSE	بطانه السقف
11.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	PORTION WORN OUT , DUST COVER PORTION DAMAGE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae