



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jun 2022, 17:57:31
Transaction Number	63337397 (CC10006)	Queue Number	312309



Chassis Number	MNTAB7A91K6010517
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sentra
Model Year	2019
Color	Grey
Mileage	108393 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH FENDER REPAINTED,PORTION REPAIRED&FRONT REFITTED	مدكار
01.B Doors	LEFT SIDE BOTH DOOR REPAINTED,PORTION REPAIRED	أبواب
01.C Bonnet	REPAINTED,REFITTED	غطاء المحرك
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Sign of back accident		وجود مؤشر لحادث في الخلف
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.H Floor	BACK PANEL ,QUATER PANEL REPAIRED	الارضية
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	JERKING ,MINOR OIL LEAK	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Chassis Condition		الشاسي
03.A Chassis Extension	RERA LEFT SIDE REPAIRED	تمديدات الشاسي

DEFECT	REMARKS	
03.B Chassis	FRONT BOTH SIDE CHASSIS REPAIRED,LEFT SIDE STILL BEND	الشاسيه
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2018/2020	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
05 Interior Condition		الحاله الداخليه
05.A AC Condition	OK	المكيف
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK,REFITTED	حالة المحرك النظري
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	FRONT UPPER MOUNT CUT	ممتص الصدمات
08 Engine Cooling System		نظام تبريد المحرك
08.A Coolant tank	WATER TANK CAP MISSING	خزان التبريد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



PENDING

Plate Details :	--
Chassis No :	MNTAB7A91K6010517
Vehicle Make :	NISSAN
Vehicle Model :	SENTRA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	108392 Kms.
Origin :	Thailand
Model Year :	2019
Gear Type :	Automatic
Engine Size :	3500 CC
Engine No :	MRA83620...
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2000 Kgs.
Empty Weight :	1600 Kgs.

⚠ Not allowed to be used as an official Doc

⚠ Please communicate with the inspection supervisor at the same testing center in order to complete your transaction

Certificate Number :	5-TAS-2022-17017455
Inspection Date :	16-06-2022
Certificate Print Date :	16-06-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 9 sec
Appointment Ref Number :	--
Start Time :	20:02
End Time :	20:09
Lane :	03
Token No. :	279
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
6 %	23 %	17 %	0.01 %
Vehicle on Petrol HC Reading			
54 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Warning triangle	Missing	Major

Pending Defect for Fixing

Issue
Warning triangle

⚠ Inspection result will be fail automatically in case the pending defects were not repaired within 4 calendar days

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	1800	

Inspection Remarks:

FRONT BOTH SIDE FRAME MEMBER & REAR RIGHT SIDE EXDTENSION REPAIRED ,, CCM DONE W/O NO. 20220-04-05-7 // FRONT BUMPER FRAME BULK HEAD FENDERS REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460	Cash	17017455	AED 170 Collected on 16/06/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

- ① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- ① Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

