

Queue Number

2841418

Transaction Date

07 Oct 2026, 13:20:22

Site Name

840 - Emirates Auctions

Transaction Number

81912455 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTDKW9D35D*****
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2013
Color	White
Mileage	518363 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.E Windshield	FRONT CRACKED	زجاج
01.F Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BUMPER FRAME ,CRASH BOX DENT.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END CRASH BOX REPAIRED ,REAR EXTENSION END DENT MINOR DENT .	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
---------------------	---------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	RUSTY.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Indicator & Hazard light	FENDER INDICATOR DAMAGED.	الاشارات
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK.	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR CONDITION DIRTY PORTION RUSTY ,SIGN OF FLOODED.	اخرى
11.B Mirror	CENTER MIRROR MISSING	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Door Panel	WORN OUT PORTION DAMAGED .	لوحة بطانة الباب
11.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

للتساوي والمقترحات يمكنك التواصل معنا عبر

