

Queue Number 2607462

Transaction Date 01 Aug 2026, 10:50:41

Site Name
840 - Emirates AuctionsTransaction Number
90632235 (CC10013) (CC10013)

Vehicle Details

Chassis Number	LJD0AA297P*****
Specification	GCC Specification
Make	Kia
Model	Pegas
Model Year	2023
Color	Red
Mileage	52962 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME , BULKHEAD , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY PORTION GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , MUDDY , PARTS GETTIG RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTAR COVER WORN OUT	حالة المقاعد
---------------------	----------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------------	----------------------

05.B Road Test	NOT CHECK	فحص علي الطريق
----------------	-----------	----------------

06 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	2023 LEFT DAMAGED	الاطار الامامي
06.B Rear Tyre	2023 BOTH SIDE	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	MINOR LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	GETTING FADED	لوحة القيادة
08.D Door Panel	PORTION FADED	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae