



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Mar 2023, 13:36:13
Transaction Number	56536454 (CC10009)	Queue Number	687250



Chassis Number	SALYA2BV1JA726393
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Vogue
Model Year	2018
Color	Silver
Mileage	75655 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bumper	REFITTED,SCRATCHES	دعامية
01.B Vehicle Model	VELAR	طراز المركبة
01.C Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Fenders	REFITTED	مدكار
01.F Bonnet	REPAINTED PORTION REPAIRED ,REFITTED	غطاء المحرك
01.G Vehicle Color	GOLDEN	لون المركبة
01.H Floor	UNDR FLOOR PARTS CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	JERKING	حالة الجير النظري
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2020 & MINOR WORN OUT	الاطار الامامي
03.B Rear Tyre	LEFT SIDE 2020, RIGHT SIDE 2019 CRACK	الاطار الخلفي

DEFECT	REMARKS	
03.C Rims Condition	SCRATCHES	حالة الجنوط
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	SIGN OIL WET	حالة المحرك النظري
<b>06 Brake Condition</b>		<b>الفرامل</b>
06.A Brake Pedal	SPONGY	دواسة الفرامل
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.