CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2993798	Transaction Date	16 Nov 2026, 16:52:29
Site Name	840 - Emirates Auctions	Transaction Number	21340640 (CC10013) (CC10011)



Vehicle Details

Chassis Number	U5YPG8141J*******
Specification	GCC Specification
Make	Kia
Model	Sportage
Model Year	2018
Color	White
Mileage	370852 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED	الصبغ
01.C Doors	REAR LEFT SIDE PORTION REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED RUST PROOFED	الارضية
01.F Bumper	RIGHT SIDE REFLECTOR DAMAGED	دعامية
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS PORTION RUST PROOFED COVERED CHECK VISIBLE AREA ONLY /OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	OIL WET , DIRTY , PARTS GETTING RUSTY , COMPONENTS REFITTED	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED,RIGHT SIDE NOT WORKING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT & MESSAGE ON DISPLAY	ضوء تحذير
08 Suspension System		**ممتص الصدمات**
08.A Arms	ARM BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		**المقود**
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		**الحاله الداخليه**
10.A Other	CENTER CONSOLE BOX COVER CRACKED / INTERIOR PARTS GETTING RUSTY	اخري
10.B AC Condition	NORMAL COOLING	المكيف
10.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING,REAR BOTH NOT WORKING FROM MAIN SWITCH PANEL	مفتاح النافذه و الزجاج
10.D Dash Board	CRACKED	لوحة القياده
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Sun Visor	RIGHT SIDE LOCK DAMAGED	حاجب الشمس
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae