

Queue Number 2830934

Transaction Date 05 Oct 2026, 15:44:59

Site Name
840 - Emirates AuctionsTransaction Number
97031721 (CC10009) (CC10012)

Vehicle Details

Chassis Number SJAAB1ZV9H*****
 Specification GCC Specification
 Make Bentley
 Model Bentayga
 Model Year 2017
 Color Blue
 Mileage 195151 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR FULLY COVERED NOT VISIBLE	الارضية
01.E Bumper	MISALIGN , GRILL PORTION DAMAGED , REAR LEFT SIDE REFLECTOR DAMAGED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	MISALIGN , OPEN BUTTON NOT WORKING PROPERLY	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED , RIGHT SIDE OUTER FRAME DAMAGED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED SLIGHTLY BEND LEFT SIDE END BRACKET CRACKED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OVERHEAT/ OIL LEAK DRIPPING PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Belt	FRONT LEFT SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	WORN OUT	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	GEAR FUALT OIL WET PARTS REFITTED MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE WORN OUT ,PORTION LOOSE	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHTS AND MESSAGES ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Other	ABS FUALT	اخرى
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
09.B Other	SUSPENSION REFITTED	اخرى
09.C Hydraulic System	NOT WORKING, DYNAMIC FUALT	النظام الهيدروليكي
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX , PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)/ ELECTRIC FUALTS	اخرى
10.B Mirror	RIGHT SIDE COVER INDICATOR PORTION CRACKED	المرآيا
10.C AC Condition	NOT COOLING , REAR DISPLAY	المكيف
10.D Roof Light	REAR RIGHT SIDE LOOSE	أنارة السقف
10.E Audio	SCREEN SCRATCHES	صوتيات
10.F Dash Board	LEATHER PORTION LOOSE , WORN OUT	لوحة القيادة
10.G Roof Ceiling	PORTION LOOSE	بطانه السقف
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae