

Queue Number 2773320

Transaction Date 19 Sep 2026, 12:59:24

Site Name
840 - Emirates AuctionsTransaction Number
28472157 (CC10013) (CC10013)

Vehicle Details

Chassis Number	WDB2200751*****
Specification	Imported
Make	Mercedes
Model	S 500
Model Year	1999
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK LOGO DAMAGED	دعامية
01.E Trunk	NOT CHECKED	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED MUDDY FULLY OILY PORTION GETTING RUSTY	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY KEY MISSING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2024 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Hand Brake	INNER LATCH DAMAGED	فرامل اليد
08.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY / CENTER CONSOLE BOX PORTION DAMAGED	اخرى
10.B Mirror	SIDE VIEW MIRROR COVER DAMAGED	المرآيا
10.C AC Condition	NOT CHECKED	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القيادة
10.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Sunroof	CURTAIN MISSING	فتحت سقف
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

