

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions** 15199136 (CC10006)

Transaction Date

13 Apr 2022, 15:23:28

Queue Number

312309



Chassis Number JMYSRCY1AGU717995

Engine Number

Vehicle Class Car

Manufacturer Mitsubishi

Model Lancer Model Year 2016

Silver Color

196487 Km Mileage

Fuel Type **Petrol**

No. Of Cylinders

GCC Specification Specification

DEFECT REMARKS

O1.A Fenders FRONT BOTH SIDE REPLACED & REAR BOTH SIDE PORTION REPAIRED, REPAINTED O1.B Doors PORTION REPAIRED, REPAINTED O1.C Bumper REPAINTED, MISALIGN O1.D Other FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED O1.E Sign of front accident REPAIRED O1.F Paint BODY PORTION REPAIRED, REPAINTED & MINOR DENT SCRATCHES, PORTION GETTING RUSTY, PORTION FADED O1.G Trunk PORTION REPAIRED, REPAINTED		
REPAIRED ,REPAINTED 01.B Doors PORTION REPAIRED,REPAINTED 01.C Bumper REPAINTED,MISALIGN 01.D Other FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED 01.E Sign of front accident REPAIRED & MINOR DENT SCRATCHES,PORTION GETTING RUSTY , PORTION FADED 01.G Trunk PORTION REPAIRED,REPAINTED	01 Body	بسم المركبة
01.C Bumper REPAINTED,MISALIGN 01.D Other FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED 01.E Sign of front accident REPAINTED & MINOR DENT SCRATCHES,PORTION GETTING RUSTY , PORTION FADED 01.G Trunk PORTION REPAIRED,REPAINTED	01.A Fenders	مدكار
01.D Other FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED 01.E Sign of front accident BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES,PORTION GETTING RUSTY , PORTION FADED 01.G Trunk PORTION REPAIRED,REPAINTED	01.B Doors	بواب
REPAIRED O1.E Sign of front accident O1.F Paint BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES,PORTION GETTING RUSTY , PORTION FADED O1.G Trunk PORTION REPAIRED,REPAINTED	01.C Bumper	عامية
O1.F Paint BODY PORTION REPAIRED, REPAINTED & MINOR DENT SCRATCHES, PORTION GETTING RUSTY, PORTION FADED O1.G Trunk PORTION REPAIRED, REPAINTED	01.D Other	خري
SCRATCHES,PORTION GETTING RUSTY , PORTION FADED 01.G Trunk PORTION REPAIRED,REPAINTED	01.E Sign of front accident	وجود مؤشر لحادث في المقدمة
	01.F Paint	لصبغ
O2 Interior Condition	01.G Trunk	عندوق
	02 Interior Condition	لحاله الداخليه
02.A AC Condition ADJUSTMENT BUTTON MISSING	02.A AC Condition	لمكيف

03 Transmission Condition الجير

03.A Road Test NOT CHECK فحص علي الطريق 03.B Visual Gear Box SIGN OF MINOR OIL LEAK حالة الجير النظرى

Condition 03.C Gear Box Mount

MOUNT RUBBER CRACKED كرسي الجير

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
04.B Mount	MOUNT RUBBER CRACKED	كرسي
05 Chassis Condition		الشاصي
05.A Chassis	OK	الشاسيه
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2014.2019 CRACKED EXPIRED	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2015 BADLY CRACKED, EXPIRED	الاطار الامامي
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.