



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jul 2022, 13:25:44
Transaction Number	56481878 (CC10006)	Queue Number	312309



Chassis Number	JN8FY15YOCX590448
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2012
Color	White
Mileage	160682 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	LOW COOLING	المكيف
01.B Dash Board	PORTION CRACKED	لوحة القيادة
01.C Roof Ceiling	LOOSE	بطانه السقف
02 Body		جسم المركبة
02.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE PORTION REPAIRED,REPAINTED & FRONT RIGHT SIDE REFITTED	مدكار
02.B Bonnet	REFITTED	غطاء المحرك
02.C Doors	RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED	أبواب
02.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
03 Suspension System		ممتص الصدمات
03.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
03.B Other	STABILIZER LINK BOOT CUT	اخرى
03.C Ball Joint	BOOT CUT	مفصل كروي
04 Engine Condition		المحرك
04.A Visual Engine Condition	MODIFIED & OPEN,REFITTED	حالة المحرك النظري

DEFECT	REMARKS	
04.B Other	AIR INTAKE MODIFIED	اخرى
04.C Smoke	WHITE SMOKE	دخان
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2016/2017 & CRACKED , EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2015/2017 CRACKED & EXPIRED	الاطار الخلفي
06 Exhaust System		نظام العادم
06.A Modification	MODIFIED, NOISY	تعديلات
07 Brake Condition		الفرامل
07.A Other	CLUTCH PEDAL HARD	اخرى
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	REFITTED	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
10 Lights		الاضاءة
10.A Brake Light	MIDDLE LIGHT BACK COVER MISSING	نور الفرامل
11 Chassis Condition		الشاسي
11.A Chassis	REAR BOTH SIDE CHASSIS BULGED	الشاسيه
11.B Chassis Number	FAIREWALL MANUFACTUR PLATE MISSING	رقم القاعدة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	G 5359 Dubai Private
Chassis No :	JN8FY15YOCX590448
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	160682 Kms.
Origin : Japan	Model Year : 2012
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : nil	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 3000 Kgs.	Empty 1100 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-17323548		
Inspection Date :	02-08-2022		
Certificate Print Date :	02-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	11 min 25 sec		
Appointment Ref Number :	--		
Start Time :	11:32	End Time :	11:44
Lane :	02	Token No. :	130
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 12 %	Parking brake imbalance between LHS and RHS 14 %	Vehicle on Petrol CO Reading 1.26 %
Vehicle on Petrol HC Reading 686 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tire change all dry crack & old	Date of manufactured tampered or expired	Major
Exhaust pipes and silencers muffler fix original	Noisy	Major

Inspection Remarks: rear chassis bulged & body bracket dent // inlet manifold modified //

Payment Details

Inspection Performed by 30544	Payment Method Cash	Transaction Number 17323548	Service Fees AED 170 Collected on 02/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

ⓘ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

ⓘ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.