CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899656
Transaction Date	28 Oct 2026, 10:08:15
Site Name	840 - Emirates Auctions
Transaction Number	23993639 (CC10026) (CC10026)



Vehicle Details

Chassis Number	KL1PJ5C56E*******
Specification	GCC Specification
Make	Chevrolet
Model	Cruze
Model Year	2014
Color	Blue
Mileage	175048 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Bonnet	MISALIGN , REFITTED	غطاء المحرك
01.F Fuel Tank	PETROL FLAP COVER MISSING	خزان الوقود
01.G Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED , PORTION DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED PARTS GETTING RUSTY , OIL LEAK , ABNORMAL NOISY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , OIL LEAK ,	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE DAMAGE	الضوء الخلفي
06.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER VIEW MIRROR FADED	المرايا
09.C AC Condition	LOW COOLING	المكيف
09.D Dash Board	PORTION DAMAGE	لوحة القياده
09.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.F Sun Visor	LEFT SIDE DAMAGE	حاجب الشمس
09.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
09.J Engine Start Button	REMOTE DAMAGE	زر تشغيل المحرك
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae