

Queue Number 2848451

Transaction Date 08 Oct 2026, 16:49:31

Site Name
840 - Emirates AuctionsTransaction Number
52119196 (CC10013) (CC10025)

Vehicle Details

Chassis Number	1FTMF1E54N*****
Specification	GCC Specification
Make	Ford
Model	F 150
Model Year	2022
Color	Grey
Mileage	42380 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	BOTH SIDE REPAINTED PORTION REPAIRED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.C Doors	BOTH SIDE REPAINTED PORTION REPAIRED REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION GETTING DIRTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED	غطاء المحرك
01.H Pillars	BOTH SIDE B/ PILLAR OUTER PAINEL REPAINTED	القوائم
01.I Sign of front accident	FRONT BUMPER FRAEM , RADIATOR SUPPORT BULK HEAD , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME RUST PROOFED / FRONT BOTH SIDE END BRACKET REPAIRED / PORTION DENT BEND / GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Smoke	MINOR WHITE	دخان
03.B Other	INTAKE PIPE AIR FILTER MODIFIED / INNER COMPARTMENT ELECTRIC WIRE UNSAFE	اخرى
03.C Engine Visual Condition	OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	RIGHT SIDE PORTION LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST MODIFIED NOISY	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR OIL LEAK ,REFITTED , PARTS GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
07.B Rear Tyre	RIGHT SIDE 2021 EXPIRED , LEFT SIDE 2022	الاطار الخلفي
08 Lights		الاضاءة
08.A Fog light	NOT WORKING	كشاف الضباب
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	MISALIGN	ازرع
09.B Arms	ARM BUSHES DRY CRACK	
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT COOLING	المكيف
10.C Roof Ceiling	PORTION LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae