



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 May 2022, 12:41:22
Transaction Number	52210422 (CC10006)	Queue Number	312309



Chassis Number	SALLAAA548A481682
Engine Number	
Vehicle Class	Car
Manufacturer	Land Rover
Model	LR3
Model Year	2008
Color	Black
Mileage	90254 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2018 WORN OUT , CRACKED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 WORN OUT , CRACKED	الاطار الخلفي
02 Interior Condition		الحاله الداخليه
02.A AC Condition	NOT COOLING	المكيف
02.B Dash Board	CRACKED	لوحة القيادة
02.C Roof Ceiling	LOOSE	بطانه السقف
03 Body		جسم المركبة
03.A Trunk	SKIRT LOOSE	صندوق
03.B Paint	PORTION REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
03.C Door Handle & Lock	FRONT LEFT SIDE COVER MISSING	مقابض الأبواب والأقفال
03.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
04 Battery Condition		حالة البطارية
04.A Battery bracket	MISSING	حامل البطارية
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	LOWER ARM BUSHES CUT	ازرع
07 Exhaust System		نظام العادم
07.A Other	CATAYLIC CONVERTER OPEN ,REWELDED	اخرى
08 Engine Condition		المحرك
08.A Visual Engine Condition	SIGN OF LEAK	حالة المحرك النظرى
08.B Smoke	MINOR WHITE SMOKE	دخان
09 Chassis Condition		الشاسي
09.A Chassis	OK	الشاسيه
10 Steering Condition		المقود
10.A Steering Oil	OIL WET	زيت المقود
11 Lights		الاضاءة
11.A Tail Light	REAR COVER CRACKED	الانارة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.