

Queue Number 2906821

Transaction Date 26 Oct 2026, 09:01:51

Site Name
840 - Emirates AuctionsTransaction Number
42002768 (CC10021) (CC10021)

Vehicle Details

Chassis Number	WBAFG4109A*****
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	2010
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		
01.A Paint	BODY ,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES .	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA.RIGHT SIDE ROCKER PANEL ,RUNNIG BOARD PORTION REPAIRED,	الارضية
01.D Bumper	MINOR SCRATCHES	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Sign of front accident	BUMPER ,BULKHEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		
02.A Chassis	CHASSISCOVERED , MUDDY,CHECKED ONLY VISIBLE AREA/OK	الشاسيه
03 Engine Condition		
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED MINOR OIL LEAK PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		
04.A Gear Box Visual Condition	NOT CHECKED REFITTED MINOR OIL LEAK PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
07 Suspension System		مفصل الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A AC Condition	NOT CHECK	المكيف
08.B Dash Board	PORTION DAMAGED	لوحة القيادة
08.C Roof Ceiling	WORN OUT	بطانة السقف
08.D Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae