



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Jan 2022, 17:52:24
Transaction Number	70552088 (CC10006)	Queue Number	312309



Chassis Number	MMBJNKA50AD018129
Engine Number	
Vehicle Class	Heavy
Manufacturer	Mitsubishi
Model	
Model Year	2010
Color	White
Mileage	251305 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Tail Light	OK	الانارة
01.B Head Light	OK	الاضاءة الرئيسية
02 Wipers and Arms		المساحات
02.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
03 Body		جسم المركبة
03.A Fenders	FRONT BOTH SIDE POERION REPAIRED & REPAINTED	مدكار
03.B Floor	REAR CARRIOR BOX PORTION REPAIRED & REPAINTED	الارضية
03.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
03.D Pillars	LEFT SIDE C/PILLAR OUTER PANEL PORTION REPAIRED, REPAINTED	القوائم
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05 Seats Condition		المقاعد

DEFECT	REMARKS	
05.A Seat Condition	PORTION DAMAGED	حالة المقاعد
06 Interior Condition		الحاله الداخليه
06.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
06.B AC Condition	OK	المكيف
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OIL LEAK	الجير
09 Engine Condition		المحرك
09.A Engine Condition	OIL LEAK	حالة المحرك
10 Suspension System		ممتص الصدمات
10.A Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
10.B Arms	FRONT BOTH SIDE CONTROL ARMS BUSHES CRACKED	ازرع
11 Steering Condition		المقود
11.A Steering Oil	OIL LEAK	زيت المقود
11.B Steering Boot	BOOT CUT & LEAK	ربلة المقود
11.C Rack Pinion	OIL LEAK	مسطرة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.