CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934056
Transaction Date	03 Nov 2026, 12:50:54
Site Name	840 - Emirates Auctions
Transaction Number	58306021 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WDCDF7DE2E*******
Specification	GCC Specification
Make	Mercedes
Model	GL 500
Model Year	2014
Color	White
Mileage	230574 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR RIGHT SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES .	الصبغ
01.C Doors	RIGHT SIDE BOTH DOORS REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN ,SCRATCHES.	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	PARTS REFITTED ,ABNORMAL NOISY ,SHAKING ,PARTS RUSTY , AIR FILTER PIPE DAMAGED.	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACKED.	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	GET JERKING ,OIL WET ,PARTS GETTING RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT & WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	HARD .	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	AIR SUSPENSION FAULT ,BODY LEVEL IMPROPER.	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED .	ربلة المقود
10.B Steering Box	MINOR OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A AC Condition	OK	المكيف
11.B Power Window Switch And Glass	MAIN SWITCH FADE.	مفتاح النافذه و الزجاج
11.C FLoor Matting	CENTER CONSOLE BOX BACK COVER DAMAGED.	فرش الأرضيه
11.D Dash Board	PORTION LOOSE.	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.F Sun Visor	LEFT SIDE MIRROR COVER MISSING	حاجب الشمس
11.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae