

Queue Number	2837365	Transaction Date	06 Oct 2026, 13:43:26
Site Name	840 - Emirates Auctions	Transaction Number	78864235 (CC10009) (CC10012)



Vehicle Details

Chassis Number	5LMCJ2C95K*****
Specification	GCC Specification
Make	Lincoln
Model	MKC
Model Year	2019
Color	White
Mileage	165071 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPELEY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bonnet	REPAINTED REPAIRED , REFITTED	غطاء المحرك
01.F Trunk	REPAINTED PORTION REPAIRED	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET REFITTED	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL WET,REFITTED GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Interior Condition		الحاله الداخليه
06.A Other	INTERIOR PARTS GETTING RUSATY	اخرى
06.B AC Condition	OK	المكيف
06.C Power Window Switch And Glass	FRONT RIGHT SIDE MAN SWITCH NOT WORKING	مفتاح النافذه و الزجاج
06.D Floor Matting	EXTRA COVER , PORTION DAMAGED	فرش الأرضيه

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae