

Queue Number 2743250

Transaction Date 15 Sep 2026, 08:55:53

Site Name
840 - Emirates AuctionsTransaction Number
93876742 (CC10021) (CC10021)

Vehicle Details

Chassis Number	WDDSJ4EB4K*****
Specification	Imported
Make	Mercedes
Model	CLA 250
Model Year	2019
Color	Red
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION GETTING RUSTY FADED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	الارضية
01.D Bumper	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	دعامية
01.E Sign of front accident	BUMPER FRAME FENDER FRAME,RADIATOR FRAME SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED	الشاسيه
--------------	-----------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED , PARTS REFITTED ,OIL LEAK ,GETTING RUSTY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK,PARTS GETTING RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
-----------------	-----------------	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Suspension System		مفصل الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae