

Queue Number 2844267

Transaction Date 07 Oct 2026, 14:14:37

Site Name
840 - Emirates AuctionsTransaction Number
38980588 (CC10013) (CC10011)

Vehicle Details

Chassis Number	1C4BJWAG7E*****
Specification	GCC Specification
Make	Jeep
Model	Wrangler
Model Year	2014
Color	Grey
Mileage	209330 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY STICKER PAINT NOT CHECK,PARTS FIBER(BODY KIT MODIFIED)	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.D Bumper	PORTION CRACK	دعامية
01.E Windshield	FRAME EXTRA BAR FITTING	زجاج
01.F Bonnet	MODIFIED REFITTED,RIGHT SIDE LOCK MISSING	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME RUST PROOFED PORTION GETTING RUSTY MINOR DENT	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY / CHECK DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Other	INTAKE PIPE MODIFIED WITH FILTER	اخرى
03.B Engine Visual Condition	REFITTED , MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER,FRONT RIGHT SIDE SEAT LOOSE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	--------------------------------	----------------------

Condition	Remarks	الحالة
05.B DIFFERENTIAL	REAR OIL LEAK	الدفرنشيل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2023 BOTH SIDE DRY CRACK	الاطار الامامي
06.B Rear Tyre	2023 BOTH SIDE DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	FADED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Brake Oil	CAP MODIFIED	زيت الفرامل
09 Suspension System		ممتص الصدمات
09.A Other	SUSPENSION PARTS REFITTED MODIFIED & BUSHES CRACK	اخرى
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY REFITTED (SIGN OF FLOODED)	اخرى
10.B AC Condition	NO COOLING	المكيف
10.C Audio	LCD NOT WORKING	صوتيات
10.D Dash Board	PORTION LOOSE	لوحة القيادة
10.E Sun Visor	BOTH SIDE BRACKET WORN OUT,MIRROR DIRTY	حاجب الشمس
10.F Steering Wheel and control buttons	WORN OUT,HORN NOT WORKING	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB PART LOOSE	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	BOTTLE DIRTY WATER TO LOW / SIGN OF MIX WITH OIL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

