



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Oct 2022, 14:47:17
Transaction Number	57086027 (CC10008)	Queue Number	598867



Chassis Number	JN8AY2NY1F9115688
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2015
Color	White
Mileage	277947 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED ,REPAINTED MINOR DENTS SCRATCHES.	الصبغ
01.B Trunk	REPAINTED	صندوق
01.C Rusty	UNDER BODY PARTS GETTING RUSTY.	صدأ
01.D Doors	RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED	أبواب
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	REFITTED	حالة الجير النظري
02.B Road Test	NOT CHECKED	فحص علي الطريق
03 Steering Condition		المقود
03.A Steering Oil	OIL LEAK	زيت المقود
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
05 Engine Condition		المحرك

DEFECT	REMARKS	
05.A Visual Engine Condition	MINOR OIL LEAK,REFITTED	حالة المحرك النظري
06 Chassis Condition		الشاسي
06.A Chassis	OK & CHASSIS PORTION GETTING RUSTY.	الشاسيه
07 Seats Condition		المقاعد
07.A Seat Condition	FRONT LEFT SIDE LOOSE.	حالة المقاعد
08 Interior Condition		الحاله الداخليه
08.A Mirror	NOT WORK PROPERLY.NOISY.	المرايا
08.B AC Condition	LOW COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.