CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2922837
Transaction Date	29 Oct 2026, 16:07:04
Site Name	840 - Emirates Auctions
Transaction Number	71896368 (CC10009) (CC10012)



Vehicle Details

Chassis Number	KMHE341G6G*******
Specification	GCC Specification
Make	Hyundai
Model	Sonata
Model Year	2016
Color	Silver
Mileage	92589 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTINTG RUSTY	صدأ
01.C Floor	FLOOR CHASSIS COVERED RUST PROOFED RUNNING BOARD SIGN OF ALIGN REAPIRED	الارضية
01.D Bonnet	REFITTED	غطاء المحرك
01.E Trunk	MISALIGN	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	TOP COVER CRACKE	اخري
03.B Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY ,SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	REAR PORTION CUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Roof Light	NOT WORKING	أنارة السقف
08.D Audio	NOT WORKING	صوتيات
08.E Dash Board	LEATHER REPALCED	لوحة القياده
08.F Roof Ceiling	REPLACED	بطانه السقف
08.G Sun Visor	BOTH SIDE LIGHT MIRROR NOT WORKING , RIGHT SIDE STAND DAMAGED	حاجب الشمس
08.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae